

## Rubber Bellow – Accessory for linear actuator ..Plus

Type	Description
GMB-2	Rubber bellow for ..Plus linear actuators with stroke length 100 mm
GMB-3	Rubber bellow for ..Plus linear actuators with stroke length 300 mm


### Mounting/Description

1. Remove fork joint if mounted
2. Pull rubber bellow over shaft (big hole is actuator side)
3. Fasten the 2 cable straps (see fig. 1.1)
4. Mount fork linkage

### Technical Data

Degree of protection	protect stroke from dust and water
Temperature range	-40...+ 100 °C
Material	Elastomer based on Chlorobutadiene rubber CR
Colour	black

### Product images / Application fig. 1.1



### Attention!

1. Avoid electrostatic discharge
2. Only wet cleaning